

# **ADJUSTAPAR LAMPS**

### MODEL

Model: 9PAR30DIM/9CCTS/BAS 9PAR30SNDIM/9CCTS/BAS 14PAR38DIM/9CCTS/BAS



#### **DIMMER COMPATIBILITY**

Model: 9PAR30DIM/9CCTS/BAS 9PAR30SNDIM/9CCTS/BAS							
Brand	Series	Model	Load (W)	Dimming Range	Dimmability		
	Lutron	MAELV-600	600	0-100%	Compatible		
	Skylark Contour	CTELV-303P	300	0-100%	Compatible		
	Diva	DVELV-300P	300	0-100%	Compatible		
Lutron	Nova	NTELV-600	600	0-100%	Compatible		
	Caseta	PD-5NE	250	0-100%	Compatible		
	Diva	DV-600P	600	0-90%	Compatible		
	Toggler	TG-600P	600	0-100%	Compatible		
	Skylark Contour	CTCL-153P	150	-	Not Compatible		
	Diva	DVCL-153P	150	0-90%	Compatible		
	Maestro C•L	MACL-153M	150	0-90%	Compatible		
	Illumatech	IPE04-1LZ	300	10-100%	Compatible*		
Leviton	Sureslide Decora	6674	600	0-90%	Compatible		
	Trimatron	6602	600	-	Not Compatible		
Cooper	Aspire	9536	1,000	0-90%	Compatible**		

\*Minimum 4 lamps \*\*Minimum 5 lamps



## **ADJUSTAPAR LAMPS**

#### DIMMER COMPATIBILITY

Model: 14PAR38DIM/9CCTS/BAS

Brand	Series	Model	Load (W)	Dimming Range	Dimmability
Lutron	Lutron	MAELV-600	600	0-100%	Compatible
	Skylark Contour	CTELV-303P	300	0-100%	Compatible
	Diva	DVELV-300P	300	0-100%	Compatible
	Nova	NTELV-600	600	10-100%	Compatible
	Caseta	PD-5NE	250	0-100%	Compatible
	Diva	DV-600P	600	0-100%	Compatible
	Toggler	TG-600P	600	0-100%	Compatible
	Skylark Contour	CTCL-153P	150	-	Not Compatible
	Diva	DVCL-153P	150	0-100%	Compatible
	Maestro C•L	MACL-153M	150	0-100%	Compatible
	Illumatech	IPE04-1LZ	300	10-100%	Compatible
Leviton	Sureslide Decora	6674	600	0-100%	Compatible
	Trimatron	6602	600	-	Not Compatible
Cooper	Aspire	9536	1,000	0-100%	Compatible***

<sup>\*\*\*</sup>Minimum 3 lamps

GREEN CREATIVE has provided this dimmer switch compatibility chart for guidance when selecting a dimmer and lamp combination. Our lamps were tested for compatibility with the above listed dimmers. Dimmers that do not appear on the chart might still be compatible but have not been tested. All testing has been performed with a stable main supply. The quality of the local main, existing installation and wiring, as well as different manufacturer versions of the above dimmers may affect dimming performance. Since no assurance can be provided regarding these factors, it is a general recommendation to perform a test on-site prior to installing the LED lamps.